



07 '05 04:20PM NAVISTAR INTERNATIONAL

P.4/14

Method For Installing... Dykema et al. 10/767,575 Docket No. D5310-DIV REPLACEMENT

1/7




FIG. 1
PRIOR ART






FIG. 2
PRIOR ART

Method For Installing... Dykema et al. 10/767,575 Docket No. D5310-DIV REPLACEMENT

2/7

**FIG. 5****FIG. 3**

Method For Installing... Dykema et al. 10/767,575 Docket No. DS310-DIV REPLACEMENT

Γ

3/7




FIG. 4





FIG. 6


Method For Installing... Dykema et al. 10/767,575 Docket No. D5310-DIV REPLACEMENT

4/7

**FIG. 9**

Method For Installing... Dykema et al. 10/767,575 Docket No. D5310-DIV REPLACEMENT

5/7

**FIG. 10**

Method For Installing... Dykema et al. 10/767,575 Docket No. D5310-DIV REPLACEMENT

6/7




FIG. 11

Method For Installing... Dykema et al. 10/767,575 Docket No. D5310-DIV REPLACEMENT

7/7




FIG. 7




FIG. 12